1285 Walt Whitman Road Melville, New York 11747–3081 United States Country Code (1) (631) 271–6200 FAX No. (631) 271–8259 http://www.ul.com

Underwriters Laboratories Inc.®

Melville – October 31, 2002

APC America, Inc. 85 Rangeway Road Building 2 Billerica, MA 01862-0318

Attn: Mr. Ev Reynolds

Reference: File E95463, Project No. 02ME21095, MAL/3013A

Subject: UL 1778 Evaluation of UPS Model SU045X283

NOTICE OF AUTHORIZATION TO APPLY UL'S (C & US LISTING MARK)

Per your request of October 9, 2002, we are adding Model SU045X283, which is a modification of Model SU045X163, to the UL Report.

Dear Mr. Reynolds,

This letter temporarily supplements the UL Follow-Up Services Inspection Procedure.

This letter serves as authorization to apply UL's (C & US Mark) to the above products, which were constructed identical to the sample products, and were submitted to UL for this investigation. The UL records covering these products will be in the UL Follow-Up Services Procedure, File E95463, Volume 1, Section 19.

To provide the manufacturer with the intended authorization to apply the UL Listing Mark you, the Applicant, must send a copy of this notice (and all attached material) to each manufacturing location covered by a Follow-Up Service Procedure.

This authorization is effective only for 90 days from the date of this Notice. Records covering your products are now being prepared and will be sent to you in the near future.

Products produced which bear the UL Mark shall be identical to those which were evaluated by UL and found to comply with UL's requirements. If changes in construction are discovered, authorization to use the UL Mark may have to be withdrawn and products that bear the UL Mark may have to be revised (in the field or at the manufacturer's facility) to bring them into compliance with UL's requirements.

If we can be of further assistance, please do not hesitate to contact us.

Sincerely.

Michael Lavorata (ext. 23290)

Sr. Project Engineer

Conformity Assessment Services E-Mail: Michael.A.Lavorata@us.ul.com Reviewed By:

oseph Rodriguez (ext. 22690)

Engineering Group Leader
Conformity Assessment Services

E-Mail: Joseph.Rodriguez@us.ul.com